CONNECTED BEAM

$V_R$

o

D

$l_w$

L

d

CLIP ANGLE
(EACH SIDE)

Ww

p

g

N = NUMBER OF
FASTENERS
PER SIDE